



**Figure 4.9** A view of Mt Victoria by Surveyor William Govett. The pass is open, but adjustments continue. In the foreground is a surveyor with a theodolite. In the background cattle are falling over a breach in the wall. [ML SLNSW]



**Figure 4.10** A view of the stone walls constructed on Mitchell's new line as it approached the Cox's River in the mid 1830s. Taken from the west looking away from the No.2 Stockade site toward Farmer's Creek. [C. Liston 2003]





**Figure 4.11** A closer view of the remnant walls between Cox's River and Farmer's Creek [C. Liston, 2003]



**Figure 4.12** This substantial stone wall uncovered during the drought of 2002 and 2003 was constructed near a water course on the road between Farmer's Creek and the Cox. It indicates the massive amount of work required to meet what are described in the correspondence as relatively minor problems, in this instance Mitchell's statement the '... a small water course has given way'. [C. Liston, 2003]